




Промрукав
Русский производитель электрики

Лоток неперфорированный Профи (1,0мм) Промрукав



<i>Тупоразмер AxHxL, мм</i>	<i>Аpm. SZ</i>	<i>Аpm. HDZ</i>	<i>Аpm. AISI 304</i>	<i>Аpm. AISI 316</i>
<i>100x50x3000</i>	<i>PR16.12781</i>	<i>PR16.13827</i>	<i>PR16.13995</i>	<i>PR16.13659</i>
<i>100x50x6000</i>	<i>PR16.12797</i>	<i>PR16.13848</i>	<i>PR16.14016</i>	<i>PR16.13680</i>
<i>100x80x3000</i>	<i>PR16.12782</i>	<i>PR16.13828</i>	<i>PR16.13996</i>	<i>PR16.13660</i>
<i>100x80x6000</i>	<i>PR16.12798</i>	<i>PR16.13849</i>	<i>PR16.14017</i>	<i>PR16.13681</i>
<i>100x100x3000</i>	<i>PR16.12780</i>	<i>PR16.13826</i>	<i>PR16.13994</i>	<i>PR16.13658</i>
<i>100x100x6000</i>	<i>PR16.12794</i>	<i>PR16.13847</i>	<i>PR16.14015</i>	<i>PR16.13679</i>
<i>150x50x3000</i>	<i>PR16.12784</i>	<i>PR16.13830</i>	<i>PR16.13998</i>	<i>PR16.13662</i>
<i>150x50x6000</i>	<i>PR16.12800</i>	<i>PR16.13851</i>	<i>PR16.14019</i>	<i>PR16.13683</i>
<i>150x80x3000</i>	<i>PR16.12785</i>	<i>PR16.13831</i>	<i>PR16.13999</i>	<i>PR16.13663</i>
<i>150x80x6000</i>	<i>PR16.12801</i>	<i>PR16.13852</i>	<i>PR16.14020</i>	<i>PR16.13684</i>
<i>150x100x3000</i>	<i>PR16.12783</i>	<i>PR16.13829</i>	<i>PR16.13997</i>	<i>PR16.13661</i>
<i>150x100x6000</i>	<i>PR16.12799</i>	<i>PR16.13850</i>	<i>PR16.14018</i>	<i>PR16.13682</i>
<i>200x50x3000</i>	<i>PR16.12787</i>	<i>PR16.13833</i>	<i>PR16.14001</i>	<i>PR16.13665</i>
<i>200x50x6000</i>	<i>PR16.12804</i>	<i>PR16.13854</i>	<i>PR16.14022</i>	<i>PR16.13686</i>
<i>200x80x3000</i>	<i>PR16.12788</i>	<i>PR16.13834</i>	<i>PR16.14002</i>	<i>PR16.13666</i>
<i>200x80x6000</i>	<i>PR16.12805</i>	<i>PR16.13855</i>	<i>PR16.14023</i>	<i>PR16.13687</i>
<i>200x100x3000</i>	<i>PR16.12786</i>	<i>PR16.13832</i>	<i>PR16.14000</i>	<i>PR16.13664</i>
<i>200x100x6000</i>	<i>PR16.12803</i>	<i>PR16.13853</i>	<i>PR16.14021</i>	<i>PR16.13685</i>